


Fiber Optic Cabling in Modern Facilities

Giannis Papaioannou CDCDP, Infrastructure Product Manager

www.space.gr

Classification ISO 27001: Public

Ethernet Roadmap



Source: The Ethernet alliance



The Strongest Team


SPACE

AFL HYPERSCALE.



Space Hellas - All Rights Reserved

Power Budget





MPO (MTP)




□ 40GBASE-SR4 (4X10G)

- □ 100GBASE-SR4 (4x25G)
- □ 400G?

Things to consider

- Transition module MPO-LC
- Test.
- Cleaning


Pre-Terms



Cleaning and Inspection


According to Cisco:

- A 1-micrometer dust particle on a single-mode core can block up to 1% of the light (a 0.05dB loss).
- A 9-micrometer speck is still too small to see without a microscope, but it can completely block the fiber core.





Fiber Count





CPR

Heat Release/ Flame spread	Aca	B1ca	B2ca	Сса	Dca	Eca	Fca
Reaction to fire	No contribution to fire growth and no smoke hazard	Combustible but has very little burning		rowth rate and heat release rate	Similar to wood, continuous flame spread, a moderate fire growth rate, and a moderate heat release rate.	Small flame attack, is not causing a large flame spread	Cables that fail Eca
Additional categories	None	Additional categories			Additional categories	None	None
Smoke ¹		s1a, s1b, s1, s2 or s3	s1a, s1b, s1, s2 or s3	s1a, s1b, s1, s2 or s3	s1a, s1b, s1, s2 or s3		
Flaming droplet/particle ²		d0, d1 or d2	d0, d1 or d2	d0, d1 or d2	d0, d1 or d2		
Acid gas ³		a1,a2 or a3	a1,a2 or a3	a1,a2 or a3	a1,a2 or a3		
AVCP	System 1+ (factory audit, regular test of product and repeat factory audits by NANDO)				System 3 (test of product by NANDO)		System 4 (test by manufacturer
Relevant to fiber optic cables	No	No Indoor or indoor/outdoor cables					Outdoor cables used in "works"

Patch cords?

Pre terms?



Space Hellas - All Rights Reserved

Thank you and always remember

TRUST,

Takes years to build, seconds to break and forever to repair...

Space Hellas is your trusted partner

